

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/21/2012 11:21 AM		4. Date/Time of Death 06/21/2012 11:21 AM		5. Fatal Case No 9				
6. Mine Information :												
a) Mining Company Name T H Kinsella Incorporated			b) Mine Name Kinsella Quarry & Mill			c) Parent of Mining Company John J Kinsella						
7. Mine Location : a) City FAYETTEVILLE			b) County Onondaga		c) State NY		8. Mine ID Number: 30-01279		9. Union: NO			
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees: a) Total 12		b) Underground 0		c) Open Pit/Quarry 6		d) Mill/Prep Plant 2		e) Other 4	
12. Contractor Name:						13. Union		14. Contractor ID Number: ZZZ				
15. Contractor Address: a) City			b) County			c) State			d) Zip Code			
16. Number of Contractor Employees: a) Total			b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:						
a) Mine Employees: 12			b) Contractor Employees: 0			a) Mine Employees: 0			b) Contractor Employees: 0			
19) Location of Accident										20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility						
21. Nonfatal Injuries: 1			22. Fatal Injuries: 1									
23. Victim Information :												
a) Name Terry C. Johnson					b) Age 49							
c) Regular Job Title: Customer												
d) Activity at Time of Accident: Driving Dump Truck												
<input checked="" type="checkbox"/> Contractor Employee												
24. Experience :												
Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days						
a) Total: 0		b) at the mine: 0		c) at activity (23d) 0		d) with Contractor 0						
25. Autopsy Performed: If Yes, Location YES Onondaga County Coroner						26. Mine Telephone No.: (315) 637-3390						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was driving a loaded dump truck down a grade when the truck went out of control. He jumped from the cab and was run over by the truck. A passenger also jumped from the cab and was treated and released from a hospital.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Studebaker			29. Model: Transtar						
30. District: M2000 Northeastern		32. Field Office: Geneva NY			33. Event Number: 6569236				
34. Accident Investigator: Matthew H. Mattison			35. MSHA Person Notified: Dennis A. Yesko			Date 06/21/2012		Time 11:43 A	
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher <i>mh</i>			Date 06/25/2012				
38. Reason For Amendment: Items 14, 23(e)									